



Figure 4

Parapet roof deck detail - tanking specification where falls are not optimum and ponding could occur